

Glove Sizing Chart

Correct sizing is essential for ensuring glove comfort. The ideal way to determine glove size is with a dressmaker's cloth tape. Use it to measure the circumference of the palm of the hand at its widest point (in mm or in inches). Cross reference that measurement against the table provided here.

Measuring hands in this manner will not account for all possible variations in hand size. For instance, the length of a worker's fingers may be longer or shorter than average. In that case, gloves that are one-half or even a full size larger or smaller than the measured hand size may fit more comfortably.

	XS	S	M	L	XL	XXL
SIZE	6	7	8	9	10	11
CUFF COLOR	Purple	Red	Yellow	Brown	Black	Lt. Blue
HAND CIRCUMFERENCE	152 mm	178 mm	203 mm	229 mm	254 mm	279 mm

