

SPECIFICATION SHEET

I1139 - ARTEX REMOVER

General Product Information:

- Should be used neat, not diluted.
- Coverage: 10 – 15M per 5litre
- Leave for no less than 1 hour (dependant on thickness/how applied)
- Painted artex should be wire brushed or sanded to allow artex to penetrate through.
- Once this has been done scrape off with a paint scraper.

The above information is given in good faith and for guidance only. The user shall be responsible for determining that the performance of the product is sufficient for his application. The quoted values are based on averages and should not be taken as maximum or minimum values for specific purposes.